

EMPLOYEE BADGE REELS

Keep Essential ID Ready

Premium Quality
Guaranteed for
100,000 Pulls!

(Patent #D539,122)



Carabiner style clip for
belt loops and bags.



Metal Slip Clip Designed For
Scrubs & Uniforms

#RBRCA "HEALTH & SAFETY"
Spot Color Imprint
30" Retractable
Carabiner Style Badge Reel

150	250	500	1,000	2,500+
2.40	2.25	2.15	2.05	1.95 (C)
	2.15	2.05	1.95	

#RBRCA4 "HEALTH & SAFETY"
PhotoImage® 4 Color Process
30" Retractable
Carabiner Style Badge Reel


150	250	500	1,000	2,500+
2.50	2.35	2.25	2.15	2.05 (C)
	2.25	2.15	2.05	



Size: 1-3/8" W x 2" H
Imprint: 7/8" W x 1 1/8" H

Packaging: Polybag
Weight: 7 lbs. (100 pcs.)

Available Colors:



RBRCA Spot Color Setup Charge: 55.00 (G) per color. **Price Includes:** One color imprint, one location. **PMS Match Charge:** 40.00 (G) per color. Each additional color add .30 (G) per color plus setup charge.

RBRCA4* Full Color Imprint Setup Charge: 55.00 (G). **Price Includes:** up to a Full Color Imprint. Exact color match on Full Color Imprint is not guaranteed.

Email Proof Charge: 7.50 (G), add 2 days to production time. **Repeat Setup Charge:** 27.50 (G). **Production Time:** 5 Days. **Product Size:** 1-3/8" W x 2" H. **Packaging:** Polybag. **Imprint Area:** Spot Color 1" W x 1-1/4" H / Full Color: 7/8" W x 1 1/8" H.

Specify Promo #E4566 to receive special pricing at time of order placement as it cannot be applied later. This offer may not be combined with any other promotion, discount, coupon and/or special column pricing (EQP & NQP do not apply sorry no exceptions). Expires 1/31/2022. All prices are in US Dollars.

Please note: Slight shifting of logo/text cannot be avoided. As each product is manufactured and logoed individually, up to 3/16" movement in logo alignment may occur. Products are intended for individual use and cannot be compared one to another. In 4-color process printing, exact color match cannot be achieved. There may be a dramatic difference between the PMS Color noted, screen color shown and printed color. None of these can be considered a defect. 1027U